

# **GREENFIELD INDUSTRIES TRAINING AGENDA**



**TDC**

# AGENDA – TUESDAY

---

- INTRODUCTION 8:00 - 8:05 AM
- COMPANY OVERVIEW 8:05 - 8:20 AM
- KNOWLEDGE ASSESSMENT 8:20 - 8:35 AM
- CUTTING TOOL MATERIALS 8:35 - 9:25 AM
- BREAK 9:25 - 9:45 AM
- BASIC DRILLS 9:45 – 11:35 AM
- LUNCH AND LEARN: WEBSITE 11:35 – 12:35 PM
- DRILL FEEDS AND SPEEDS 12:35 - 12:55 PM
- **DEMO-DRILLS** #1 & #1A 1:05 PM – 1:35 PM
- PLANT TOUR 1:35 - 2:35 PM
- **DEMOS DRILLS** #2, 3, 4 2:35 – 3:05 PM
- CARBIDE DRILLS 3:15 – 3:35 PM
- DRILL SITUATIONS (CASE STUDIES) 3:35 - 4:05 PM
- BASIC REAMERS 4:05 – 4:35 PM



# AGENDA – WEDNESDAY

---

- END MILLS 8:00 – 9:30 AM
- CARBIDE END MILLS 9:30 - 9:40 AM
- END MILL FEEDS AND SPEEDS 9:40 – 10:00 AM
- **DEMO END MILLS** #1, #2 10:10 - 10:30 AM
- END MILLS SIT. (CASE STUDIES) 10:40 – 11:10 AM
- BASIC TAPS 11:10 AM – 12:40 PM
- LUNCH AND LEARN GREENTECH 12:40 – 1:40 PM
- BASIC TAPS 1:40 – 2:10 PM
- TAP TROUBLESHOOTING 2:10 – 3:25 PM
- **DEMOS TAPS** #1 3:35 – 3:50 PM
- TAP FEEDS AND SPEEDS 4:00 – 4:10 PM
- THREAD MILLS 4:10– 5:10 PM
- **DEMO-THREAD MILLS** (Video) 5:10 – 5:20 PM
  
- DINNER 6:30 PM



# AGENDA – THURSDAY AM

---

- HOLE SAWS AND SAW BLADES 8:00 – 8:20 PM
- BURRS AND EXTENSION BURRS 8:20 – 8:35 PM
- PERFORMANCE TOOLS
  - High Speed DRILLS Unique Tools 8:35 - 8:50 AM
  - PM Endmills 8:50 - 9:10 AM
  - HP Solid Carbide End Mills 9:10 - 9:20 AM
  - END MILL SIT. (CASE STUDIES) 9:20 - 10:05 AM
  - **DEMO** 538/539 #1 10:15 - 10:30AM
  - BREAK 10:30 AM – 10:40 AM
  - **DEMO**-VARIABLE INDEX #2 10:40 – 10:55 AM
  - HP Taps 11:05 – 11:15 AM
  - **DEMO**-HP TAPS #3 (Video) 11:15– 11:25 AM
  - TAP SIT. (CASE STUDIES) 11:25 – 11:55 AM
- KNOWLEDGE ASSESSMENT 11:55 - 12.10 PM
- LUNCH 12:10 PM
- DEPART

